

FireFox® 1 F - 2

Spare part kit: 145 8202 - Air piston seal set for FireFox® 1F

Spare part no.	Article no.	Designation
87	143 6007	Piston seal
93	143 5680	O-ring
88	143 6006	Guide ring 4
90	143 5660	O-ring
92	144 6027	Snap ring
91	143 5659	Rod seal

Spare part kit: 145 8179 - Distributing valve complete for FireFox® 1 F, 2, 2 F

Spare part no.			Article no.	Designation
FireFox® 1 F	FireFox® 2	FireFox® 2 F		
60	92	61	143 6297	Distributing valve complete
62	94	63	144 5285	Snap ring
61	93	62	145 1053	Stopper complete

Spare part kit: 145 7720 - Grip seal set for FireFox® 1 F, 2, 2 F

Spare part no.			Article no.	Designation
FireFox® 1 F	FireFox® 2	FireFox® 2 F		
64	66	65	143 5472	Flat gasket 1
69	71	70	143 5480	Flat gasket 2
85	89	86	143 5486	O-ring

Spare part kit: 145 8180 - Air piston seal set for FireFox® 2 - 2 F

Spare part no.		Article no.	Designation
FireFox® 2	FireFox® 2 F		
89	88	143 6226	Piston seal
95	94	143 5839	O-ring
90	89	143 6235	Guide ring
92	91	143 5834	O-ring
94	93	144 6082	V-profile ring
93	92	143 5635	Airzet Rod seal

GBM 95

Spare part kit: 145 7517 - Seal set for GBM 95

Spare part no.	Article no.	Designation
48	143 5179	Rod seal
11	145 6749	Annular piston complete
33	143 4221	Flat gasket
17	143 4226	O-ring
14	143 4227	O-ring
10	145 7551	Sealing ring mount complete
46	145 7555	O-ring with supporting ring
12	145 7575	Cylinder sleeve, complete

We reserve the right to make changes for the entire catalogue. We do not accept liability for errors or misprints.

The applicable terms and conditions of guarantee shall apply and can be viewed under following link:
www.gesipa.com/agb

Damages resulting from natural wear and tear, overloading, use of unsuitable batteries or inexperienced handling will be excluded from the guarantee. Damages resulting from material or manufacturing faults will be repaired or replaced free of charge. Claims can only be accepted if the complete riveting tool is returned to the distributor or GESIPA®.